SF series three-phase ac permanent magnetism synchronous servo motor

# **Use and Maintenance Instructions**

Xianfeng Motor

Motor pioneer

Wuxi Xianfeng Electric Manufacturing Co., Ltd.

## 1. General

SF series sine ac permanent magnetism servo motors adopt super high intrinsic coercive force rare-earth permanent magnetic material, and it has high demagnetization resistant ability. The motor has an aluminum casing and a forced ventilation fan, and it has the advantages of compact structure, high power density, small rotor inertia, quick reacting speed and so on. The motor has a high-precision encoder element which was matched with relevant servo driving device to compose the spindle servo driving system. The low speed torque has small pulsation, and the high speed operation is stable.

#### 2. Model Explanations

SF 18 35 - 10

SF: SF series ac permanent magnetism servo motor

- 18: The flange outer diameter of the motor installation (marked digital ×10, mm)
- 35: The motor rated torque (N  $\cdot$  m)
- 10: The motor rated speed (marked digital  $\times$  100, rpm)

# 3. Reception check

· You should check this SF series motor when you receive and open it.

• Check if there were damages during the transportation, rotate the motor spindle by hand and it should be freely rotated (because a oil seal was assembled on the motor shaft extension end, it is normal that there will be a little retardation when you rotate it).

. Besides the motor and this operating instructions, check whether other accessories you ordered are complete.

· Check whether the motor nameplate is in accordance with the products you ordered.

## 4. Handling and storage

- · This product must be handled with care to prevent collision.
- $\cdot$  Do not hit the motor spindle, avoid to damage the bearing and encoder.
- · Do not forced pulling the motor outgoing lines, so as to avoid the motor operation fault.

. The motor storage temperature is -15  $^\circ \rm C$  to 40  $^\circ \rm C$  , the relevant humidity should be no more than 85%.

• When the motor junction box cover was open, do not drizzle any liquids in it.

#### 5. Operating Environment

- . The motor should be installed indoors with good ventilation and with out direct sun light.
- · No corrosive and combustible gas.
- . The ambient temperature is 0  $\,^{\circ}$ C to 40 $\,^{\circ}$ C.
- The relevant humidity is 20% to 80% (no condensation)
- · Altitude above sea level shall not exceed 1000M.

#### 6. Safety and Matters Need Attention

. Check the motor with tramegger before use, the motor three phase Leading wire to motor casing insulation resistance should be no less than  $5M\Omega$ .

• The motor spindle center should be in accordance with the mechanical equipment center when being assembled, or else it may cause vibrations and noises, even cause the motor damages when it is serious.

. The motor should be tested with no load together with the driving device before operating, and connect the fan power (the motor and fan power rated voltage is three phase 380V) to confirm whether the motor and driving device is good. The fan rotating direction should be in accordance with the arrow mark on the end.

#### 7. Use and Maintenance

· Read this instruction carefully before use.


• There should be no burnt flavor, abnormal noises and overheat (temperature rise less than 100K) during the motor operating.

• When the motor was put into use after being stalled in a period of time, you should re-check the insulation and test run before you reuse it.

• The motor should have good earthing during the use.


. It is normal that there were statics on the motor surface during operating.

# 8. Connecting Terminal Configuration



# The following is the motor wiring diagram of SF180 series


The following is the motor wiring diagram of SF250 series



Motor Model T	Rated Torque	Rated Power kW	Rated Curren t A	Rated Speed r/min	Rated Freque ncy Hz	rotationa 1 inertia	Motor poles	Ke Vs	Windir resistan	-	Weight	Dimensi on	
	N•m					<b>g</b> • m <sup>2</sup>	2p	vs	Ohm		kg		В
电机 型号	额定转矩	额定功率	额定电流	额定转速	额定频率	转动惯量	电机极数	Ke	绕组 电阻 Ohm	重量	外	外形尺寸	
	N*m	kW	A	r/min	Hz	g*m <sup>3</sup>	Reference and the second	Vs		kg	A		B
SF1835-10	)	3.7	7.4	1000	66.7	5.2	8	3.23	4.25	34		-	
SF1835-20	35	7.3	14.9	2000	133.3		8	1.66	1.11		344	1	145
SF1835-30	22	11	22.3	3000	200	1.34	8	1.07	0.47		S. Low	-	
SF1853-10		5.6	11.2	1000	66.7	7.6	8	3.21	2.29	40			180
SF1853-20	53	11.1	22.5	2000	133.3		8	1.60	0.58		380		
SF1853-30	U	16.7	33.8	3000	200	11.00	8	1.09	0.27				
SF1870-10		7.3	14.9	1000	66.7	9.7	8	3.29	1.65	46	100		215
SF1870-20	70	14.7	29.8	2000	133.3		8	1.64	0,42		416		
SF1870-30		22	44.7	3000	200		8	1.07	0.18		1	1	
SF1888-10		9.2	18.7	1000	66.7	11	8	3.39	1.30	53		1.4	250
SF1888-20	88	18.4	37.4	2000	133.3		8	1.69	0.33		452		
SF1888-30		27.6	56.2	3000	200		8	1.09	0.14				
SF18105-10	)	11	22.3	1000	66.7	13	8	3.24	0.92	59	6		290
SF18105-20	105	22	44.7	2000	133.3		8	1.60	0.23		488		
SF18105-30	)	33	67.1	3000	200		8	1.14	0.12		1 20		
SF18132-10		12.9	26.2	1000	66.7	15	8	3.22	0.78	66			
SF18132-20	123	25.8	52.4	2000	133.3		8	1.69	0.22		524		325
SF18132-30		38.6	78.6	3000	200		8	1.10	0.10				
SF18140-10		14.7	29.8	1000	66.7		- 8	3.10	0.62	72	1 01	-	
SF18140-20	140	29.3	59.6	2000	133.3	17	8	1.55	0.16		560		360
SF18140-30		44	89.4	3000	200	1000	8	1.07	0.08		het		

Parameter list of SF180 series three-phase ac permanent magnetism synchronous servo motor


**SF180 series motor dimensional drawing** (the flange installation is standard configuration, the foot installation should be custom made) unit: mm



Motor Model	Rated Torque N•m	Rated Power kW	Rated Current A	Rated Speed r/min	Rated Frequen cy Hz	rotational inertia g • m <sup>2</sup>	Motor poles 2p	Ke Vs	Winding resistance Ohm	Weig ht	Dimension	
										kg	А	В
电机 型号	額定 转矩 N·m	额定	额定	额定	频率 惯量 极数	and the second se	电机	Ke	绕组	重量	外形尺寸	
		功率 kW	电流 A	转速 r/min		极数 2p	及数 Vs	电阻 Ohm	kg	Α	в	
SF25104-10	104	10.9	22	1000	66.7	20	8	3.18	0.935		1 gtal	180
SF25104-20		21.8	44	2000	133.3		8	1.57	0.234	80	428	
SF25104-30		32.7	66	3000	200		8	1.10	0.114			
SF25156-10	156	16.3	33	1000	66.7	27	8	3.05	0.476	92	468	220
SF25156-20		32.7	66	2000	133.3		8	1.64	0.139			
SF25156-30		49	99	3000	200	1.000	8	1.05	0.057		1 million	
SF25208-10	208	21.8	44	1000	66.7	35	8	3.12	0.331		508	260
SF25208-20		43.6	88	2000	133.3		8	1.64	0.085	104		
SF25208-30		65.4	133	3000	200		8	1.09	0.040			
SF25260-10	260	27.2	55	1000	66.7	42	8	3.12	0.242	116	548	300
SF25260-20		54.5	111	2000	133.3		8	1.56	0.061			
SF25260-30		81.7	166	3000	200		8	1.07	0.029			
SF25312-10	312	32.7	66	1000	66.7	50	8	3.27	0.210	128	588	340
SF25312-20		65.4	133	2000	133.3		8	1.63	0.052			
SF25312-30		98	199	3000	200		8	1.05	0.021			
SF25364-10	364	38.1	77	1000	66.7	57	8	3.26	0.175	140		380
SF25364-20		76.2	155	2000	133.3		8	1.63	0.043		628	
SF25364-30		114.4	232	3000	200		8	1.09	0.019			
SF25416-10		43.4	88	1000	66.7	1.046	8	3.11	0.135	152		420
SF25416-20	416	87.1	177	2000	133.3	65	8	1.56	0.033		668	
SF25416-30		130.7	265	3000	200	0.5	8	1.09	0.016			

Parameter list of SF250 series three-phase ac permanent magnetism synchronous servo motor

**SF250 series motor dimensional drawing** (the flange installation is standard configuration, the foot installation should be custom made) unit: mm



# Appendix

Motor rotating is	• Check whether the three phase power line is well connected				
not stable	• Whether the voltage deviation is within the range of $\pm 10\%$				
	•Check whether the encoder line is well connected and whether there is break				
_	line				
Abnormal noises	• Check whether the motor axis center is in accordance with the mechanical				
in the motor	equipment center				
	• Check whether all the mechanical parts are tightly connected				
	• Check whether there are foreign matters which may interfere with the				
	mechanical rotating parts				
	• Check whether the bearing has abnormal noises or if it is over				
	(temperature less than 95°C).				
Motor overheat	• Check whether the ambient temperature is too high and whether it is				
	well-ventilated.				
	•Check whether the fan rotation is good and whether you can feel obvious air				
	flowing when you put your hand on the motor front shoulder (do not touch				
	the motor to avoid scald).				
	• Check whether the loads are higher that the rated value.				
	Check whether there were too much dusts and foulings				

# Wuxi Xianfeng Electric Manufacturing Co., Ltd.

Address: Luoshe Town, Huishan District, Wuxi, Jiangsu.

 Tel: 0510-83311008
 83311074

 Fax: 0510-83311007
 83310535

 Post code: 214187
 Email: web@shengling88.com

 Http: www.shengling88.com
 Http: www.shengling88.com

 Internet Keyword: Xianfeng Motor